## **Application Data She t**

**Application Information** 

Application number:: Not Yet Assigned

Application Type:: Regular

Subject Matter:: Utility

Suggested Group Art Unit:: N/A

CD-ROM or CD-R?:: None

Sequence submission?:: None

Computer Readable Form (CRF)?:: No

Title:: METHOD FOR DIAGNOSING INCORRECT

VALVE LIFT ADJUSTMENT IN AN INTERNAL COMBUSTION ENGINE

Attorney Docket Number:: 449122058100

Request for Early Publication?:: No

Request for Non-Publication?:: No

Small Entity?:: No

Petition included?:: No

Secrecy Order in Parent Appl.?:: No

**Applicant Information** 

Applicant Authority Type:: Inventor

Primary Citizenship Country:: Germany

Status:: Full Capacity

Given Name:: Frank

Family Name:: WEISS

City of Residence:: Grasslfing

Country of Residence:: Germany

Street of mailing address:: Igelbergweg 5

City of mailing address:: Pentling/GrassIfing

Country of mailing address:: Germany

Postal or Zip Code of mailing address:: 93080

Applicant Authority Type::

Inventor

Primary Citizenship Country::

China

Status::

**Full Capacity** 

Given Name::

Hong

Family Name::

**ZHANG** 

City of Residence::

Tegernheim

Country of Residence::

Germany

Street of mailing address::

Spitzweg Straße 16

City of mailing address::

Tegernheim

Country of mailing address::

Germany

Postal or Zip Code of mailing address::

93105

**Correspondence Information** 

Correspondence Customer Number::

25227

**Representative Information** 

Representative Customer Number::

25227

**Foreign Priority Information** 

Country:

Application number:

Filing Date:

Priority Claimed:

Germany

10230899.3

07/09/02

Yes